

Fire Safety Report – Cardinal Hall

Prepared by HCC Safety Committee

Separate Documentation: Fire Log Fire Drill Reports Cardinal Hall Housing Manual		This information is also available at: http://www.hibbing.edu/faculty-staff/eservices.html under Safety Information	
Reporting Requirements	Description	Resource	Other
Statistics showing: 1) number of fires and cause, 2) number of injuries related to fire, 3) number of deaths related to fires, 4) value of property damaged.	Please refer to the Cardinal Hall fire log.	This information is also available at: http://www.hibbing.edu/faculty-staff/eservices.html under Safety Information	
Description of each on-campus student housing facility fire safety system.	Cardinal Hall has a complete sprinkler system and fire extinguishers in each unit and in common areas. Smoke detectors and evacuation routes are posted in every unit. Pull stations are located in hallways and common areas. Both sprinklers and extinguishers are subject to yearly/monthly inspection.	Cardinal Hall inspection checklists Maintenance logs	
Number of regular, mandatory, supervised fire drills.	Cardinal completes 2 fire drills per semester (6 per year)	A Fire Drill Report is completed and submitted to the Associate Dean of Student Services and the HCC Safety Committee.	
Policies on electrical appliances, smoking, open flames, etc.	Cardinal Hall is apartment-living style housing and has full kitchens including stove/oven and microwave.	Refer to Cardinal Hall Housing manual for policies on open flames, hazardous appliances, smoking, etc.	
Plans for future improvements	None at this time		